	HBJAYWALK			COMM	D LOGS				50>
TO .	ADIC	PRFO !		CACTUS	CACTUS		CITE		<b></b> 50>
	TOR: 04092	21 D	EC 63	/				IN 55642	
		!							
FO			,	*					POST PRO 1997 PO
CTION: OSA 1-20						ROUTIN	INE		
MOS	•		•			8		]16	50X
)	: DIRECTOR					6 7	MD RB	14 15	50
						<u></u> 5	Batel DFA	19	************************
	Ø345 Z 21 DE	C 63		SEC	RET	3	4 deg - F14		
ATE	69 A F 60 6 A 9 B 10	)					Commo	9	

ABLE RESEARCH TO SOLVE IT. DO KNOW THAT SUPPLY REEL ARM WAS SOURCE OF MALFUNCTION AND FOR TIME BEING MUST ASSUME IT WAS OF TEMPORARY NATURE. BENCH TESTS SHOW THAT RECORDER OPERATES, BUT WITH SLIGHT CHANGE IN TENSION ON THIS ARM.

END OF MESSAGE

DOCUMENT NO.

NO CHANGE IN CLASS.

DECLASSIFIED

CLASS. CHANGED TO: TS S C

NEXT REVIEW DATE:

AUTH: HR, 70-2

DATE: /7/9/8/ REVIEWER: 064540

SECRET

GROUP 1
Excluded from automoti
downgrading and
declarationalise